



On December 6, 2009, a customer was using the Citibank ATM located at 22000 Ventura Bl, Woodland Hills, CA 91364. He discovered a skimmer on the machine that he was using. He also observed a second skimmer on the machine next to him. The customer called the police and the skimmers were recovered.

It should be noted that the skimmer was designed to fit over the existing card slot and contained the card reader and the camera in one device.



The real card reader slot.

The capture device



The side cut out is not visible when on the ATM.



This is the back side of the device.

The card reader is on the left and the camera is tucked into the right side as shown below.

The device may have been constructed with parts from an MP3 Player.

It was attached with several small pieces grey double-sided tape

The part was well made and fit nicely over the original card reader.

